



HYUNDAI Technical Service Bulletin

Group	CAMPAIGN
Number	09-01-033
Date	NOVEMBER, 2009
Model	GENESIS COUPE (BK)

Subject
MANUAL TRANSMISSION GEAR SHIFT KNOB REPLACEMENT (CAMPAIGN T98)

CIRCULATE TO:	<input type="checkbox"/> GENERAL MANAGER	<input checked="" type="checkbox"/> PARTS MANAGER	<input checked="" type="checkbox"/> TECHNICIAN
<input checked="" type="checkbox"/> SERVICE ADVISOR	<input checked="" type="checkbox"/> SERVICE MANAGER	<input checked="" type="checkbox"/> WARRANTY MGR	<input type="checkbox"/> SALES MANAGER

IMPORTANT: THIS CAMPAIGN APPLIES TO DEALER STOCK VEHICLES ONLY.

IMPORTANT: DEALERS MUST PERFORM THIS CAMPAIGN ON ALL AFFECTED VEHICLES PRIOR TO CUSTOMER RETAIL DELIVERY. ACCESS HYUNDAI MOTOR AMERICA'S "WARRANTY VEHICLE INFORMATION" SCREEN VIA WEBDCS TO IDENTIFY OPEN CAMPAIGNS.

DESCRIPTION:

This bulletin provides the procedure for replacing the manual transmission gear shift knob.

VEHICLES AFFECTED - VERIFY THAT THE VEHICLE IS IDENTIFIED AS HAVING AN OPEN CAMPAIGN VIA WEBDCS:

Model: Genesis Coupe (BK) with manual transmission.

Applicable vehicle production date range: December 18, 2008 to June 1, 2009

PARTS REQUIRED:

Part	Remarks
	Knob - Gear shift lever P/N: 43711-2M100-QQH

SERVICE PROCEDURE:

NOTE: Before conducting the procedure, verify that the vehicle has an open campaign 09-01-033 identified on WEBDCS.

1. Undo the gear shift lever book button (A) and remove the gear shift lever knob (B) by turning it counterclockwise.





HYUNDAI Technical Service Bulletin

Group

CAMPAIGN

Number

09-01-033

2. Install the new gear shift lever knob (C). Properly align the gear position diagram on the shift knob.
3. Re-button the shift boot.



WARRANTY CLAIM INFORMATION:

Op Code	Description	Op Time
90B056R0	Manual Transmission Gear Shift Lever Knob Replacement	0.3 M/H

NOTE 1: Submit claim on Campaign Entry Screen.