



HYUNDAI Technical Service Bulletin

Group	CAMPAIGN
Number	09-01-034
Date	NOVEMBER, 2009
Model	GENESIS COUPE (BK)

Subject
**CONSOLE ARMREST REPLACEMENT
 (SERVICE CAMPAIGN T99)**

CIRCULATE TO:	<input type="checkbox"/> GENERAL MANAGER	<input checked="" type="checkbox"/> PARTS MANAGER	<input checked="" type="checkbox"/> TECHNICIAN
<input checked="" type="checkbox"/> SERVICE ADVISOR	<input checked="" type="checkbox"/> SERVICE MANAGER	<input checked="" type="checkbox"/> WARRANTY MGR	<input type="checkbox"/> SALES MANAGER

IMPORTANT: THIS UPDATE IS FOR DEALER STOCK VEHICLES ONLY.

IMPORTANT: DEALERS MUST PERFORM THIS CAMPAIGN ON ALL AFFECTED VEHICLES PRIOR TO CUSTOMER RETAIL DELIVERY. ACCESS HYUNDAI MOTOR AMERICA'S "WARRANTY VEHICLE INFORMATION" SCREEN VIA WEBDCS TO IDENTIFY OPEN CAMPAIGNS.

DESCRIPTION:

CONDITION

Some Genesis Coupe vehicles may exhibit the condition where the center console armrest lid may not be latching.

REPAIR


Replace the center console armrest assembly with the newly improved one.

APPLICABLE VEHICLES:

Model: Genesis Coupe (BK)

Applicable Vehicle Production Date Range: February 1, 2009 through May 15, 2009

PARTS INFORMATION:

PART NAME	PART NUMBER	PHOTOGRAPH
Armrest - Console	846602M5009PQQH *846602M0009PQQH (Red Stitching)	

***APPLICABLE FOR 2.0L VEHICLE WITH TRACK.**

SERVICE PROCEDURE:

1. Open the console armrest and remove the armrest hinge cover (A).

CAUTION: Be careful not to damage the armrest hinge cover.



2. Remove the armrest mounting screws (4EA).





HYUNDAI Technical Service Bulletin

Group

CAMPAIGN

Number

09-01-034

3. Install the new console armrest in reverse order of removal.



WARRANTY INFORMATION:

OP CODE	OPERATION	OP TIME
90B055R0	CONSOLE ARMREST REPLACEMENT	0.3 M/H

NOTE: Submit a campaign claim entry screen.