



HYUNDAI Technical Service Bulletin

Group	CAMPAIGN
Number	09-01-036
Date	DECEMBER, 2009
Model	GENESIS COUPE (BK) ELANTRA TOURING (FD)

Subject
**AUDIO LCD LABEL REPLACEMENT
(SERVICE CAMPAIGN TA1)**

CIRCULATE TO:	<input type="checkbox"/> GENERAL MANAGER	<input checked="" type="checkbox"/> PARTS MANAGER	<input checked="" type="checkbox"/> TECHNICIAN
<input checked="" type="checkbox"/> SERVICE ADVISOR	<input checked="" type="checkbox"/> SERVICE MANAGER	<input checked="" type="checkbox"/> WARRANTY MGR	<input type="checkbox"/> SALES MANAGER

IMPORTANT: THIS CAMPAIGN APPLIES TO DEALER STOCK ONLY.

IMPORTANT: DEALERS MUST PERFORM THIS CAMPAIGN ON ALL AFFECTED VEHICLES PRIOR TO CUSTOMER RETAIL DELIVERY. ACCESS HYUNDAI MOTOR AMERICA'S "WARRANTY VEHICLE INFORMATION" SCREEN VIA WEBDCS TO IDENTIFY OPEN CAMPAIGNS.

DESCRIPTION:

This bulletin provides the procedure for replacing the audio LCD labels (with information on how to operate the audio and adjust the clock) on some GENESIS Coupes (BK) and Elantra Touring (FD) vehicles.

APPLICABLE VEHICLES:

Model: Genesis Coupe (BK) / Elantra Touring (FD)



Applicable Vehicle Production Date Range:

- Genesis Coupe (BK): December 19, 2008 to October 23, 2009
- Elantra Touring (FD): May 28, 2009 to November 16, 2009

PARTS INFORMATION:

GENESIS COUPE (BK)

- LCD Label for audio units w/ a 6-Disc Changer





PREVIOUS	NEW
<p>TO LOAD CD: 1. PRESS "LOAD" BUTTON 2. WAIT FOR "INSERT" DISPLAY 3. INSERT CD</p> 	<p>TO LOAD CD: 1. PRESS "LOAD" BUTTON 2. WAIT FOR "INSERT" DISPLAY 3. INSERT CD</p>  <p>SOUND, XM, CLOCK, AUTO VOLUME, TEMP, TEXT, BLUETOOTH SETUP :</p> <p>1. PRESS "SETUP" BUTTON</p> <p>2. PRESS "SEEK", "SEEK", "TUNE", "TUNE" BUTTON TO CHANGE SOUND SETTING XM DISPLAY CLOCK SETTING AUTO VOLUME OUTSIDE TEMP DISPLAY TEXT SCROLL BLUETOOTH SETTING</p> <p>✳ USING THE "ENTER" BUTTON TO SELECT AND CONFIRM. ✳ RETURN : EXIT SETUP</p> <p>3. PRESS "SETUP" BUTTON TO EXIT</p>

- LCD Label for audio units w/ a single disc player

PREVIOUS	NEW
<p>NO LABEL</p>	<p>SOUND, XM, CLOCK, AUTO VOLUME, TEMP, TEXT, BLUETOOTH SETUP :</p> <p>1. PRESS "SETUP" BUTTON</p> <p>2. PRESS "SEEK", "SEEK", "TUNE", "TUNE" BUTTON TO CHANGE SOUND SETTING XM DISPLAY CLOCK SETTING AUTO VOLUME OUTSIDE TEMP DISPLAY TEXT SCROLL BLUETOOTH SETTING</p> <p>✳ USING THE "ENTER" BUTTON TO SELECT AND CONFIRM. ✳ RETURN : EXIT SETUP</p> <p>3. PRESS "SETUP" BUTTON TO EXIT</p>

ELANTRA TOURING (FD)

- LCD Label for audio units w/ a single disc player

PREVIOUS	NEW
<p>NO LABEL</p>	<p>EQUALIZER, XM, CLOCK, TIME, TEXT, AUTO VOLUME, TEMP SETUP :</p> <p>1. PRESS "SETUP" BUTTON () .</p> <p>2. ROTATE AND PUSH THE "TUNE" KNOB () FOR MENUS. AUDIO EQUALIZER XM DISPLAY CLOCK SETTING TIME DISPLAY TEXT SCROLL AUTO VOLUME OUTSIDE TEMP DISPLAY</p> <p>✳ USING THE "TUNE" KNOB () TO SELECT AND CONFIRM .</p> <p>3. PRESS "SETUP" BUTTON () TO EXIT.</p>



HYUNDAI Technical Service Bulletin

Group

CAMPAIGN

Number

09-01-036

SERVICE PROCEDURE:

1. Verify that the audio is a 6-Disc changer model or a single disc player model by identifying the logo located on the top right corner of the audio.



2. Remove the current audio LCD label from the audio LCD.



3. Apply the appropriate new label on the audio LCD.

NOTE: DO NOT remove the audio LCD labels until the vehicle is delivered to the customer.



WARRANTY INFORMATION:

OP CODE	OPERATION	OP TIME
90B057R1	AUDIO LCD LABEL REPLACEMENT/ATTACHMENT (Dealer Stock only)	0.3 M/H

NOTE: Submit claim on Campaign Claim Entry Screen.